

# LAB – GPS for Color

**L** = Lightness

**A** = - Green + Red

**B** = - Blue + Yellow


Example: Gray: 57, 0, -1

L

100 = White

0 = Black

A B



FREE ProcessControl.com

www.freeprocesscontrol.com

603.498.4553

[ron@ronellisconsulting.com](mailto:ron@ronellisconsulting.com)

© 2009 Ron Ellis